KRAMER

K-Bar Camera Bracket Quick Start Guide

This guide helps you install and use your **K-Bar Camera Bracket** for the first time.

Go to **www.kramerav.com/downloads/K-Bar** to download the latest user manual and check if firmware upgrades are available.

Step 1: Check what's in the box

☑ **K-Bar** Camera Bracket   ☑ 1 Quick start guide

Step 2: Get to know your K-Bar Camera Bracket

Bracket Screw Hole

Bracket Handle

Step 3: Mount Camera Bracket

Attach the **Camera Bracket** to the lower part of **K-Bar** to mount the camera onto a display.

To attach the Camera Bracket:

1. Attach the **Camera Bracket** to the lower part of the **K-Bar**, using the screw supplied with the **K-Bar** wall mount kit (included in the **K-Bar** package).

2. Once the bracket is connected, move the bracket handle to the desired angle.

HDMI™
HIGH-DEFINITION MULTIMEDIA INTERFACE

P/N: 2900-301538QS   Rev: 1

3. Place the **K-Bar** onto the display.

4. Press the handle against the rear side of the display to ensure that the bracket is tightly secured.

⚠️
- Before moving the display, take care to remove the Camera Bracket to prevent the K-Bar from falling.
- Once installed, do not move the bracket to the sides or push it in any way.
- Ensure that the environment (e.g., maximum ambient temperature & air flow) is compatible for the device.
- Avoid uneven mechanical loading.
- Reliable earthing of rack-mounted equipment should be maintained.

Technical Specifications

Environmental Conditions	Operating Temperature	0° to +40°C (32° to 104°F)
	Storage Temperature	-40° to +70°C (-40° to 158°F)
	Humidity	10% to 90%, RHL non-condensing
Regulatory Compliance	Safety	CE
	Environmental	RoHs, WEEE
Enclosure	Type	Aluminum
General	Net Dimensions (W, D, H)	15.9cm x 14.2cm x 1.3cm (6.3" x 5.6" x 0.5")
	Shipping Dimensions (W, D, H)	17.5cm x 14.7cm x 2.5cm (6.9" x 5.8" x 1")
	Net Weight	0.28kg (0.6lbs) approx.
	Shipping Weight	0.33kg (0.7lbs) approx.

Specifications are subject to change without notice at www.kramerav.com

CE ♻ 22 PAP